



**Map Update Notification for Pioneer In-dash Navigation Receivers:  
AVIC-8100NEX, AVIC-7100NEX, AVIC-6100NEX, and AVIC-5100NEX**

April 21, 2015

**Dear Valued Pioneer Customer:**

We would like to inform you of the availability of a critical map update for Pioneer AVIC-8100NEX, AVIC-7100NEX, AVIC-6100NEX, and AVIC-5100NEX in-dash navigation receivers sold in the United States and Canada. **This map update provides missing address data for the Delaware, Maryland, and Washington D.C. areas.** The update does not apply to any other Pioneer models.

In order to perform this update, the following items are needed:

- Pioneer navigation receiver: AVIC-8100NEX, AVIC-7100NEX, AVIC-6100NEX, or AVIC-5100NEX
- A USB storage device with at least **8 GB** of storage capacity formatted to FAT32
- Naviextras<sup>®</sup> ToolBox software, available free of charge from Naviextras.com (<http://pioneer.naviextras.com/shop/portal>)
- Windows<sup>®</sup> PC

**How to Obtain the Free Map Update:**

- Download and review the map update **instructions** to a Windows PC from the Pioneer website: [pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware)

**Questions**

If you have difficulty with any of the above or otherwise have questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through [parts.pioneerelectronics.com/contact](http://parts.pioneerelectronics.com/contact).

Sincerely,

**Pioneer Electronics (USA) Inc.**